


## User Manual



**K6** Multiplex transmission system  
Keyboard instructions

### Packing list

• manual X1 • USB Cable X1 • Keyboard X1

### Keyboard connection method


• Type\_c to Type\_c

### Keyboard indicator

1. When the keyboard power supply, the indicator is red.
2. Once the keyboard is identified, the display of the transmitter will show the last decimal point.


### Functions of the keys are as follows

### Keys description



### Functions description

- Numbers Key 1-10  
Num Key + Numbers Key 11-20
- |               |                    |
|---------------|--------------------|
| 1 Red         | Num+1 LightSkyBlue |
| 2 Green       | Num+2 Fuchsia      |
| 3 Blue        | Num+3 DarkBlue     |
| 4 Yellow      | Num+4 DarkMagenta  |
| 5 Purple      | Num+5 LightYellow  |
| 6 Cyan        | Num+6 OrangeRed    |
| 7 White       | Num+7 Lavender     |
| 8 Orange      | Num+8 LawnGreen    |
| 9 Crimson     | Num+9 SandyBrown   |
| 0 GreenYellow | Num+0 DeepPink     |



### Operation instruction

1. The number key is light on, it indicates the current number.
2. "\*" Key shows light on as default, press "\*" key shows Light on/Blink/Breath/Light off in turn, it will return to light on mode.
3. "+/-" Key, Adjust the headset volume, 2-3 second delay, 15 level maximum, short press, one level each time; long press, volume changes continuously.
4. When "\*" Key is in blinking mode, press "Enter" key, change to fast blinking; press again for slow blinking.
5. Press "\*" Key, The headset will be restored the initial channel light.
6. Disconnect the keyboard with transmitter, the last decimal point on the display of the transmitter is off, then the headset is restored the initial channel light.